PRINTED: 12/15/2009 FORM APPROVED

Bureau of Health Care Quality & Compliance

AND DIAN OF CODDECTION 1		(X1) PROVIDER/SUPPLIER/G IDENTIFICATION NUMB	PROVIDER/SUPPLIER/CLIA DENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING		(X3) DATE SURVEY COMPLETED	
NVN18ADA				B. WING		C 12/03/2009		
NAME OF PROVIDER OR SUPPLIER			STREET ADD	RESS, CITY, STA	ATE, ZIP CODE	•		
				740 IDAHO STREET LKO, NV 89801				
(X4) ID PREFIX TAG	SUMMARY ST. (EACH DEFICIENC' REGULATORY OR I		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE		
D 000	0 Initial Comment			D 000				
	Surveyor: 21044 The findings and conclusions of any investigation by the Health Division shall not be construed as prohibiting any criminal or civil investigations, actions or other claims for relief that may be available to any party under applicable federal, state or local laws.  This Statement of Deficiencies was generated as a result of a Complaint Investigation conducted from 11/5/09 to 12/3/09. This State Licensure survey was conducted by the authority of NRS 449.150, Powers of the Health Division.							
	Complaint #NV00023560 is substantiated.							
D 131 SS=G	NAC 449.129(2) Construction Standards  2. Each facility must comply with all currently adopted life safety, fire, health division, local building and zoning codes. If there is a difference between state and local codes, the more stringent standards apply.		D 131					
	Surveyor: 21044 Based on interviews f facility failed to compl chaining an exit door Findings include: The bureau received Assistant State Fire M Assistant State Fire M received a report from	of met as evidenced by: from 11/5/09 to 12/3/09 by with state fire codes leads to shut.  a telephone report from Marshal on 11/5/09. The Marshal stated that his control the local fire department and the factorical issue at the factorical states.	e, the by					

If deficiencies are cited, an approved plan of correction must be returned within 10 days after receipt of this statement of deficiencies.

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

PRINTED: 12/15/2009 FORM APPROVED

Bureau of Health Care Quality & Compliance STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING B. WING **NVN18ADA** 12/03/2009 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **3740 IDAHO STREET VITALITY CENTER ELKO. NV 89801** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE **PREFIX PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) D 131 Continued From page 1 D 131 early in the morning of 11/3/09. The Assistant State Fire Marshal reported the firemen arrived and found the front doors were chained shut. The Assistant State Fire Marshal reported he sent an officer to the facility to investigate and that officer substantiated the report. The State Fire Marshal (SFM) officer sent to the facility to investigate the incident reported in an interview that on 11/3/09 at 3:30AM, a local fire captain noticed the front exit doors were chained shut and facility staff had to unlock the chain to let them in. The SFM officer stated the fire captain instructed facility staff to stop using the chains before they left. The SFM officer further reported that he went to the facility later that evening at 10:00PM on the same day (11/3/09) and discovered the chain was still on the front exit door. Multiple photographs were taken. The SFM officer stated when facility staff were asked about the chain, they informed him that the administrator told them to place the chain on the front door to keep the dogs from jumping up on the crash bar. When the dogs jumped on the crash bar, the door would open allowing people to enter the facility after hours. The facility has been fined by the State Fire Marshal for a violation of egress standards pursuant to the 1996 International Fire Code. which the State of Nevada has adopted. This finding is a violation of the facility's health facilities license. Severity: 3 Scope: 1